

























0116631 x21 Ø0.36x0.01x25.75" Ø9,2x0,25x654 mm	0120203 x28 Ø0.2x1.18" Ø5x30 mm	0121620 x6 Ø0.47/Ø0.31x0.06" Ø12/Ø8x1,5 mm	0122005 x4 Ø0.55/Ø0.35x0.61" Ø14/Ø9x15,5 mm	0123006 x2 25 pcs 0.06x0.98" 1,4x25 mm
0125215 x6 Ø0.12x0.47" Ø3x12 mm	0125412 x6 Ø0.12x0.63" Ø3x16 mm	0125604 x7 Ø0.2x1.5" Ø5x38 mm	0126033 x7 Ø0.25x1.06" Ø6,3x27 mm	0126230 x3 M4x0.87" M4x22 mm
0131513 x18 Ø0.30x1.73/1.34" Ø7,5x44/34 mm	0131571 x12 Ø0.24xØ0.94/x0.52" Ø6,2x24/13,2 mm	0131687 x18 Ø0.59x0.37" Ø15x9,5 mm	0133203 x4 1x0.37x0.51" 25,4x9,5x13 mm	0162403 x4 M6x0.79" M6x20 mm
0181009 x3 Ø1.1x0.83" Ø28x21 mm	0192816 x3 1.89x0.61x0.51" 48x15,5x13 mm	0192817 x3 Ø1.77x0.47x0.04" 45x12x1 mm		




x3






1249x700x2,5mm




1152x236x18mm




1152x236x18mm

01051 x3




210x180x15mm


01052 x3



210x180x15mm




667x379,5x15mm




778x272x18mm

76463 x3




266x48x32mm

76464 x3




266x48x32mm

76461




766x48x32mm


76462




766x48x32mm



670x93x15mm




778x272x18mm



766x266x18mm


1	0120203 x8 Ø0.2x1.18" Ø5x30 mm	
--	--	---



2

0131513


x4




Ø0.30x1.73/1.34"


Ø7,5x44/34 mm











The diagram illustrates the assembly of two panels, labeled H and F, using screws. Panel H is positioned above panel F. Callouts show the correct placement and depth of the screws. A large inset at the bottom left shows a detailed view of a screw being inserted into a hole in panel F. A smaller inset at the top right shows a detailed view of a screw being inserted into a hole in panel H. The main diagram shows the screws being inserted into the holes in panel F. The screws are shown being inserted into the holes in panel F. The screws are shown being inserted into the holes in panel F. The screws are shown being inserted into the holes in panel F.


8 / 32

70309



3

0131571

x12




Ø0.24xØ0.94/x0.52"
Ø6,2x24/13,2 mm




4

0121620

x6




Ø0.47/Ø0.31x0.06"
Ø12/Ø8x1,5 mm



5

0125412

x6




Ø0.12x0.63"

Ø3x16 mm


0192816


x3



1.89x0.61x0.51"

48x15,5x13 mm







6



0120203


x8




Ø0.2x1.18"


Ø5x30 mm








7

0133203

1x0.37x0.51"
25,4x9,5x13 mm



x4



8

0125604


x7








Ø0.2x1.5"
Ø5x38 mm

0126033

x3




Ø0.25x1.06"
Ø6,3x27 mm








9

0131513

x8




Ø0.30x1.73/1.34"
Ø7,5x44/34 mm



10


0122005


x4



Ø0.55/Ø0.35x0.61"

Ø14/Ø9x15,5 mm






11


0162403


x4



M6x0.79"

M6x20 mm






15 / 32

70309

12

0125215


x6



Ø0.12x0.47"
Ø3x12 mm

0131513


x6








Ø0.30x1.73/1.34"
Ø7,5x44/34 mm

0192817

x3



Ø1.77x0.47x0.04"
45x12x1 mm




EA x3


13

0120203



x12





Ø0.2x1.18"
Ø5x30 mm



01052 x3




01051 x3




14

0116631


x21




Ø0.36x0.01x25.75"
Ø9,2x0,25x654 mm




01052



01051



x3



15

0131687

x6


Ø0.59x0.37"

Ø15x9,5 mm

1

2


3



16

0126230


x3







M4x0.87"
M4x22 mm

0181009

x3



Ø1.1x0.83"
Ø28x21 mm




x3




17




0131687

x2



Ø0.59x0.37"
Ø15x9,5 mm











19

0131687

x2




Ø0.59x0.37"
Ø15x9,5 mm






20

0131687

x4




Ø0.59x0.37"
Ø15x9,5 mm






21

0131687

x4





Ø0.59x0.37"
Ø15x9,5 mm





22

0126033

x4




Ø0.25x1.06"
Ø6,3x27 mm





23

0123006





x2




0.06x0.98"
1,4x25 mm




XX=YY




28 /32





1





2



3



x2



25

