



# LOUNGE CHAIR




---




538958




NEN 581




RS (1x)




LS (1x)




RS (1x)




LS (1x)




SCR (1x)




SCL (1x)




SC (2x)




F1 (1x)




BC1 (1x)




B1 (1x)




S1 (1x)



NA (2x)



NB (2x)






J (12x)

K (2x)



M (14x)

P (1x)



+ Extra



1



2




NA




NB

3





Click

6x





RS




4






5




6




7




8






9



10





11





12





13



14